



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **US/UL/QAR06.0010/11** Page 1 of 1
QAR Free Ref. No.: **4790094963** Status: **Issued**
Details of change: **Reassessment Audit** Date of issue: **2022-08-16**
Site(s) audited: **Otto Engineering Inc.** Valid until: **2025-09-28**
2 East Main Street
Carpentersville, IL 60110 Audit date: **2022-06-14**
United States of America

Issuing ExCB: **UL - UL LLC**

Manufacturer: **Otto Engineering Inc.**
2 East Main Street
Carpentersville, IL 60110

Location of
Manufacturer: **United States of America**

Product information: **Audio Accessories**

Protection concept: **Intrinsic Safety "i"**

Related QARs:

US/UL/QAR06.0010/00	US/UL/QAR06.0010/01	US/UL/QAR06.0010/02
US/UL/QAR06.0010/03	US/UL/QAR06.0010/04	US/UL/QAR06.0010/05
US/UL/QAR06.0010/06	US/UL/QAR06.0010/07	US/UL/QAR06.0010/08
US/UL/QAR06.0010/09	US/UL/QAR06.0010/10	

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEX FMG 14.0030 issue: 0	IECEX FMG 14.0030 issue: 1	IECEX FMG 14.0030X issue: 2
IECEX FMG 14.0030X issue: 3	IECEX FMG 15.0018X issue: 0	IECEX FMG 15.0018X issue: 1
IECEX FMG 15.0018X issue: 2	IECEX UL 06.0008X issue: 1	IECEX UL 06.0008X issue: 2
IECEX UL 06.0008X issue: 3	IECEX UL 06.0009X issue: 1	IECEX UL 09.0022X issue: 0
IECEX UL 09.0022X issue: 1	IECEX UL 09.0022X issue: 2	IECEX UL 09.0022X issue: 3
IECEX UL 09.0022X issue: 4	IECEX UL 09.0022X issue: 5	IECEX UL 19.0066 issue: 0
IECEX UL 19.0066 issue: 1	IECEX UL 20.0041 issue: 0	IECEX UL 21.0063 issue: 0
IECEX UL 22.0016 issue: 0		

Comments: